


Surface Defect Report (Multi Dents/Bumps)


TITLE or DENT Name

Report Details

Project Name	panoLite	Tool Number		Report Date	09. Mrz 21
Created By	Operator X	Scan Date	09. Mrz 21	Registration / Tail No.	[Registration]
Work Order No.	[WOnumber]	Flight Hours	[FlightHours]	Serial / MSN	[AircraftSerial]
Carrier	[Carrier]	Flight Cycle	[FlightCycles]		
Comments					

Screenshot





Standard safety margin: 15 mm (0.59 in.)

Dent / Bump Measurement			Unit mm		Safety Margin		15.0 mm
ID	Defect	Deviation	Small Diameter	Big Diameter	Ratio	Closest Dent ID	Distance
101	Dent	-0,85	60,9	74,6	72	106	77,2
102	Dent	-0,46	50,5	53,7	110	107	60,4
103	Dent	-0,32	42,6	52,6	132	107	170,7
104	Dent	-0,66	62,8	69,1	96	105	74,9
105	Dent	-0,47	55,9	76,2	118	104	74,9
106	Dent	-0,48	35,2	46,4	74	107	50,2
107	Dent	-0,65	49,0	59,3	76	106	50,2

